Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number
EDR ID Number

 1295
 MANHOLE 30178
 NY Spills
 S106015083

 East
 HAMPTON AVE / OCEAN AVE
 N/A

> 1 BROOKLYN, NY

1.658 mi. 8756 ft.

Relative: SPILLS:
Higher Name: MAN

Higher Name: MANHOLE 30178

Actual: Address: HAMPTON AVE / OCEAN AVE

Actual: Address: HAMPTON AVE / OCEA
2 ft. City,State,Zip: BROOKLYN, NY

Spill Number/Closed Date: 0302803 / 2005-05-23

0302803 Facility ID: Facility Type: ER DER Facility ID: 113312 Site ID: 131520 DEC Region: 2 Spill Cause: Unknown Spill Class: C4 2401 SWIS: Spill Date: 2003-06-16 Investigator: SKARAKHA Referred To: Not reported Reported to Dept: 2003-06-16 CID: 205

Water Affected: Not reported

Spill Source: Commercial/Industrial

Spill Notifier: Responsible Party

Cleanup Ceased: Not reported

Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 2003-06-16
Spill Record Last Update: 2005-05-23
Spiller Name: CALLER
Spiller Company: CON ED

Spiller Address: 4 IRVING PLACE

Spiller Company: 001
Contact Name: CALLER

DEC Memo: "E2MIS 148760 6/16/03 Vincent Castelli # 75517 Splicer, UG, reports

while doing Maintenance work found 1 qt dielectric fluid on 4 gallons of water in MH30178. States cable or jt is blown and has dfaulted structure # 210. Has turned into Fdr Control Rep. At this time feeder # has not been identified. No fire/smoke involved. No sewers or waterways affected. No private property affected. Sample has been taken and marked E priority - chain of custody # AA27206. Substance owned by Con Ed. Env. stop tag # 18982 placed. Parking only Sat & Sun. Clean up pending test results and safe access. Update - 6/16/03 Notified CIG P. Didonato @1336hr 6-16-02 22:27HRS LAB SEQ#

03-05014-001 26 PPM. S.PACE 49874. 6-17-03 02:45HRS J. IOCCO (ENV

OPS) REPORTS, DOUBLE WASHED STRUCTURE WITH BIO GEN 760 UNABLE TO GO INTO HOLE DUE TO D-FAULT TO CEMENT SUMP. TAG LEFT IN PLACE. S.PACE 49874. UPDATE 4/15/04 13:27 B. TUDY REPORTS DOUBLE WASHED STRUCTURE WITH BIO-GEN 760 AND REMOVED ALL DEBRIS...CLEAN-UP IS COMPLETE....FOD ON LOCATION MAKING REPAIRS...ENV TAG LEFT IN PLACE UNTILL FOD IS

COMPLETE Update - 4/15/04 1530hrs Tag remains in place pending UG to make repairs to default which will be done 3-11 shift this date. FOD

marked feeder. UPDATE 4/16/04 13:33 HRS AS PER D HEARNS AND FDR REP

J.SANTORA UG COMPLETED ALL REPAIRS AND PULLED THE ENV STOP TAG "

MAP FINDINGS Map ID Direction

Distance

EDR ID Number Elevation Site Database(s) EPA ID Number

> Remarks: "1QT ON 400 GALLONS WATER. PENDING RESULTS."

All Materials:

Site ID: 131520 Operable Unit ID: 870552 Operable Unit: 01 Material ID: 507256 Material Code: 0541A Material Name: dielectric fluid Case No.: Not reported Material FA: Petroleum Quantity: 1.00 Units: G Recovered: .00

Oxygenate: Not reported